

ESRF Double Crystal Monochromator - Feedback Controller

Dehaeze Thomas

June 2, 2022

Contents

1	Estimation of Sensitivity Function	3
1.1	Load Data	3
1.2	Controller	3
1.3	Test	5
2	System Identification	6
2.1	Identification ID24	6
2.2	Identification	7
2.3	Identification - New	13
2.4	Identification - White noise	16
2.5	Test	21
2.6	New controller - Higher bandwidth	22
2.7	Added gain	23
3	Noise Budgeting	28
3.1	No Displacement	28
3.2	Scans	30
3.3	Noise budgeting - No rotation	32
3.4	Noise budgeting - Bragg rotation	33
4	Test Mode C	34
4.1	Mode B and Mode C	34
5	Export numerator and denominator	36
5.1	Export	36
5.2	Verify	36

1 Estimation of Sensitivity Function

1.1 Load Data

Two scans are performed:

- 1.1 in mode B
- 3.1 in mode C

The difference between the two is that mode C adds the feedback controller.

```
%% Load Data of the new LUT method  
Ts = 0.1;  
  
ol_drx = 1e-9*double(h5read('xanes_0003.h5','/1.1/measurement/xtal_111_drx_filter')); % Rx [rad]  
cl_drx = 1e-9*double(h5read('xanes_0003.h5','/3.1/measurement/xtal_111_drx_filter')); % Rx [rad]  
  
ol_dry = 1e-9*double(h5read('xanes_0003.h5','/1.1/measurement/xtal_111_dry_filter')); % Ry [rad]  
cl_dry = 1e-9*double(h5read('xanes_0003.h5','/3.1/measurement/xtal_111_dry_filter')); % Ry [rad]  
  
t = linspace(Ts, Ts*length(ol_drx), length(ol_drx));
```

By comparison the frequency content of the crystal orientation errors between mode B and mode C, it is possible to estimate the Sensitivity transfer function (Figure 1.1).

```
win = hanning(ceil(1/Ts));  
  
[pxx_ol_drx, f] = pwelch(ol_drx, win, [], [], 1/Ts);  
[pxx_cl_drx, ~] = pwelch(cl_drx, win, [], [], 1/Ts);  
  
[pxx_ol_dry, ~] = pwelch(ol_dry, win, [], [], 1/Ts);  
[pxx_cl_dry, ~] = pwelch(cl_dry, win, [], [], 1/Ts);
```

1.2 Controller

```
load('X_tal_cage_PID.mat', 'K');
```




Figure 1.1: Estimation of the sensitivity transfer function magnitude




Figure 1.2: Bode Plot of the Controller

1.3 Test

```
Matlab _____  
Ts = 5e-3;  
cl_drx = 1e-9*double(h5read('xanes_0003.h5','/16.1/measurement/xtal_111_drx_filter')); % Rx [rad]  
ol_drx = 1e-9*double(h5read('xanes_0003.h5','/18.1/measurement/xtal_111_drx_filter')); % Rx [rad]  
t = linspace(Ts, Ts*length(ol_drx), length(ol_drx));
```

```
Matlab _____  
figure;  
hold on;  
plot(t, ol_drx)  
plot(t, cl_drx)
```

```
Matlab _____  
win = hanning(ceil(10/Ts));  
[pxx_ol_drx, f] = pwelch(ol_drx, win, [], [], 1/Ts);  
[pxx_cl_drx, ~] = pwelch(cl_drx, win, [], [], 1/Ts);
```

2 System Identification

2.1 Identification ID24

```
load('test_id_id24_3.mat')
```

```
t = 1e-4*ones(size(fjpur, 1), 1);  
  
ur.dz = fjpur(:,1) - mean(fjpur(:,1));  
ur.dry = fjpur(:,2) - mean(fjpur(:,2));  
ur.drx = fjpur(:,3) - mean(fjpur(:,3));  
ur.u = fjpur(:,7) - mean(fjpur(:,7));  
  
uh.dz = fjpuh(:,1) - mean(fjpuh(:,1));  
uh.dry = fjpuh(:,2) - mean(fjpuh(:,2));  
uh.drx = fjpuh(:,3) - mean(fjpuh(:,3));  
uh.u = fjpuh(:,8) - mean(fjpuh(:,8));  
  
d.dz = fjpd(:,1) - mean(fjpd(:,1));  
d.dry = fjpd(:,2) - mean(fjpd(:,2));  
d.drx = fjpd(:,3) - mean(fjpd(:,3));  
d.u = fjpd(:,9) - mean(fjpd(:,9));
```

```
J_a_311 = [1, 0.14, -0.0675  
           1, 0.14, 0.1525  
           1, -0.14, 0.0425];  
  
J_a_111 = [1, 0.14, -0.1525  
           1, 0.14, 0.0675  
           1, -0.14, -0.0425];  
  
ur.y = [J_a_311 * [-ur.dz, ur.dry,-ur.drx]']';  
uh.y = [J_a_311 * [-uh.dz, uh.dry,-uh.drx]']';  
d.y = [J_a_311 * [-d.dz, d.dry, -d.drx]']';
```

```
%% Sampling Time and Frequency  
Ts = 1e-4; % [s]  
Fs = 1/Ts; % [Hz]  
  
% Hannning Windows  
win = hanning(ceil(1*Fs));
```

```
%% And we get the frequency vector  
[G_ur, f] = tfestimate(ur.u, ur.y, win, [], [], 1/Ts);  
[G_uh, ~] = tfestimate(uh.u, uh.y, win, [], [], 1/Ts);  
[G_d, ~] = tfestimate(d.u, d.y, win, [], [], 1/Ts);
```

```
Matlab _____
[coh_ur, ~] = mscohere(ur.u, ur.y, win, [], [], 1/Ts);
[coh_uh, ~] = mscohere(uh.u, uh.y, win, [], [], 1/Ts);
[coh_d, ~] = mscohere(d.u, d.y, win, [], [], 1/Ts);
```

2.2 Identification

```
Matlab _____
ur = load('FJPUR_step.mat');
uh = load('FJPUH_step.mat');
d = load('FJPD_step.mat');
```

```
1   dz311
2   dry311
3   drx311
4   dz111
5   dry111
6   drx111
7   fjpur
8   fjpuh
9   fjpd
10  bragg
```

```
Matlab _____
ur.time = ur.time - ur.time(1);
ur.allValues(:, 1) = ur.allValues(:, 1) - mean(ur.allValues(ur.time<1, 1));
ur.allValues(:, 2) = ur.allValues(:, 2) - mean(ur.allValues(ur.time<1, 2));
ur.allValues(:, 3) = ur.allValues(:, 3) - mean(ur.allValues(ur.time<1, 3));

t_filt = ur.time > 48 & ur.time < 60;

ur.u = ur.allValues(t_filt, 7);
ur.y_111 = [-ur.allValues(t_filt, 1), ur.allValues(t_filt, 2), ur.allValues(t_filt, 3)];
```

```
Matlab _____
uh.time = uh.time - uh.time(1);
uh.allValues(:, 1) = uh.allValues(:, 1) - mean(uh.allValues(uh.time<1, 1));
uh.allValues(:, 2) = uh.allValues(:, 2) - mean(uh.allValues(uh.time<1, 2));
uh.allValues(:, 3) = uh.allValues(:, 3) - mean(uh.allValues(uh.time<1, 3));

uh.u = uh.allValues(t_filt, 8);
uh.y_111 = [-uh.allValues(t_filt, 1), uh.allValues(t_filt, 2), uh.allValues(t_filt, 3)];
```

```
Matlab _____
d.time = d.time - d.time(1);
d.allValues(:, 1) = d.allValues(:, 1) - mean(d.allValues(d.time<1, 1));
d.allValues(:, 2) = d.allValues(:, 2) - mean(d.allValues(d.time<1, 2));
d.allValues(:, 3) = d.allValues(:, 3) - mean(d.allValues(d.time<1, 3));

d.u = d.allValues(t_filt, 9);
d.y_111 = [-d.allValues(t_filt, 1), d.allValues(t_filt, 2), d.allValues(t_filt, 3)];
```

```

Matlab
J_a_111 = [1,  0.14, -0.0675
            1,  0.14,  0.1525
            1, -0.14,  0.0425];

J_a_311 = [1,  0.14, -0.1525
            1,  0.14,  0.0675
            1, -0.14, -0.0425];

ur.y = [J_a_311 * ur.y_111'];
uh.y = [J_a_311 * uh.y_111'];
d.y  = [J_a_311 * d.y_111'];

```

```

Matlab
%% Sampling Time and Frequency
Ts = 1e-4; % [s]
Fs = 1/Ts; % [Hz]

% Hannning Windows
win = hanning(ceil(5*Fs));

```

```

Matlab
%% And we get the frequency vector
[G_ur, f] = tfestimate(ur.u, ur.y, win, [], [], 1/Ts);
[G_uh, ~] = tfestimate(uh.u, uh.y, win, [], [], 1/Ts);
[G_d, ~] = tfestimate(d.u, d.y, win, [], [], 1/Ts);

```

```

Matlab
[coh_ur, ~] = mscohere(ur.u, ur.y, win, [], [], 1/Ts);
[coh_uh, ~] = mscohere(uh.u, uh.y, win, [], [], 1/Ts);
[coh_d, ~] = mscohere(d.u, d.y, win, [], [], 1/Ts);

```




Figure 2.1: Coherence

```

Matlab
%% Previously used controller
load('X_tal_cage_PID.mat', 'K');

```




Figure 2.2: Bode Plot of the DCM dynamics in the frame of the fast jack.

```

Matlab
%% Controller design
s = tf('s');

% Lead
a = 4; % Amount of phase lead / width of the phase lead / high frequency gain
wc = 2*pi*20; % Frequency with the maximum phase lead [rad/s]

% Low Pass Filter
w0 = 2*pi*100; % Cut-off frequency [rad/s]
xi = 0.4; % Damping Ratio

Kb = eye(3)*(2*pi*20)^2/(s^2) *1/(sqrt(a))* (1 + s/(wc/sqrt(a)))/(1 + s/(wc*sqrt(a))) * 1/(1 + 2*xi/w0*s + s^2/w0^2);;

```




Figure 2.3: Loop gain

Compare Sensitivity functions

```

Matlab
L = zeros(3, 3, length(f));
Lb = zeros(3, 3, length(f));

for i_f = 1:length(f)
    L(:,:,i_f) = [G_ur(i_f,:); G_uh(i_f,:); G_d(i_f,:)]*freqresp(K , f(i_f), 'Hz');
    Lb(:,:,i_f) = [G_ur(i_f,:); G_uh(i_f,:); G_d(i_f,:)]*freqresp(Kb, f(i_f), 'Hz');
end

```




Figure 2.4: Loop gain




Figure 2.5: Comparison of sensitivity functions




Figure 2.6: Root Locus

2.3 Identification - New

```
Matlab
ur = load('FJPUR_step_new.mat');
uh = load('FJPUH_step_new.mat');
d = load('FJPD_step_new.mat');
```

```
1  dz311
2  dry311
3  drx311
4  dz111
5  dry111
6  drx111
7  fjpur
8  fjpuh
9  fjpd
10 bragg
```

```
Matlab
ur.time = ur.time - ur.time(1);
ur.allValues(:, 1) = ur.allValues(:, 1) - mean(ur.allValues(ur.time<0.1, 1));
ur.allValues(:, 2) = ur.allValues(:, 2) - mean(ur.allValues(ur.time<0.1, 2));
ur.allValues(:, 3) = ur.allValues(:, 3) - mean(ur.allValues(ur.time<0.1, 3));

t_filt = ur.time < 5;

ur.u = ur.allValues(t_filt, 7);
ur.y_111 = [-ur.allValues(t_filt, 1), ur.allValues(t_filt, 2), ur.allValues(t_filt, 3)];
```

```
Matlab
uh.time = uh.time - uh.time(1);
uh.allValues(:, 1) = uh.allValues(:, 1) - mean(uh.allValues(uh.time<0.1, 1));
uh.allValues(:, 2) = uh.allValues(:, 2) - mean(uh.allValues(uh.time<0.1, 2));
uh.allValues(:, 3) = uh.allValues(:, 3) - mean(uh.allValues(uh.time<0.1, 3));

uh.u = uh.allValues(t_filt, 8);
uh.y_111 = [-uh.allValues(t_filt, 1), uh.allValues(t_filt, 2), uh.allValues(t_filt, 3)];
```

```
Matlab
d.time = d.time - d.time(1);
d.allValues(:, 1) = d.allValues(:, 1) - mean(d.allValues(d.time<0.1, 1));
d.allValues(:, 2) = d.allValues(:, 2) - mean(d.allValues(d.time<0.1, 2));
d.allValues(:, 3) = d.allValues(:, 3) - mean(d.allValues(d.time<0.1, 3));

d.u = d.allValues(t_filt, 9);
d.y_111 = [-d.allValues(t_filt, 1), d.allValues(t_filt, 2), d.allValues(t_filt, 3)];
```

```
Matlab
J_a_111 = [1,  0.14, -0.0675
           1,  0.14,  0.1525
           1, -0.14,  0.0425];

J_a_311 = [1,  0.14, -0.1525
           1,  0.14,  0.0675
           1, -0.14, -0.0425];
```

```

ur.y = [J_a_311 * ur.y_111]';
uh.y = [J_a_311 * uh.y_111]';
d.y = [J_a_311 * d.y_111]';

```

```

% Sampling Time and Frequency
Ts = 1e-4; % [s]
Fs = 1/Ts; % [Hz]

% Hannning Windows
win = hanning(ceil(5*Fs));

```

```

% And we get the frequency vector
[G_ur, f] = tfestimate(ur.u, ur.y, win, [], [], 1/Ts);
[G_uh, ~] = tfestimate(uh.u, uh.y, win, [], [], 1/Ts);
[G_d, ~] = tfestimate(d.u, d.y, win, [], [], 1/Ts);

```

```

[coh_ur, ~] = mscohere(ur.u, ur.y, win, [], [], 1/Ts);
[coh_uh, ~] = mscohere(uh.u, uh.y, win, [], [], 1/Ts);
[coh_d, ~] = mscohere(d.u, d.y, win, [], [], 1/Ts);

```

```

% Previously used controller
load('X_tal_cage_PID.mat', 'K');

```

```

% Controller design
s = tf('s');

% Lead
a = 4; % Amount of phase lead / width of the phase lead / high frequency gain
wc = 2*pi*20; % Frequency with the maximum phase lead [rad/s]

% Low Pass Filter
w0 = 2*pi*100; % Cut-off frequency [rad/s]
xi = 0.4; % Damping Ratio

Kb = eye(3)*(2*pi*20)^2/(s^2) *1/(sqrt(a))* (1 + s/(wc/sqrt(a)))/(1 + s/(wc*sqrt(a))) * 1/(1 + 2*xi/w0*s + s^2/w0^2);

```

Compare Sensitivity functions

```

L = zeros(3, 3, length(f));
Lb = zeros(3, 3, length(f));

for i_f = 1:length(f)
    L(:,:,i_f) = [G_ur(i_f,:); G_uh(i_f,:); G_d(i_f,:)]*freqresp(K, f(i_f), 'Hz');
    Lb(:,:,i_f) = [G_ur(i_f,:); G_uh(i_f,:); G_d(i_f,:)]*freqresp(Kb, f(i_f), 'Hz');
end

```




Figure 2.7: Comparison of sensitivity functions




Figure 2.8: Root Locus

2.4 Identification - White noise

```
ur = load('fjpur_white_noise.mat');
uh = load('fjpuh_white_noise.mat');
d = load('fjpd_white_noise.mat');
```

1 dz111
2 dry111
3 drx111
4 fjpur
5 fjuh
6 fjpd
7 bragg

```
ur.time = ur.time - ur.time(1);
ur.drx = ur.drx - mean(ur.drx);
ur.dry = ur.dry - mean(ur.dry);
ur.dz = ur.dz - mean(ur.dz);
```

```
uh.time = uh.time - uh.time(1);
uh.drx = uh.drx - mean(uh.drx);
uh.dry = uh.dry - mean(uh.dry);
uh.dz = uh.dz - mean(uh.dz);
```

```
d.time = d.time - d.time(1);
d.drx = d.drx - mean(d.drx);
d.dry = d.dry - mean(d.dry);
d.dz = d.dz - mean(d.dz);
```

```
J_a_111 = [1, 0.14, -0.0675
           1, 0.14, 0.1525
           1, -0.14, 0.0425];
ur.y = [J_a_111 * [-ur.dz, ur.dry, ur.drx]'];
uh.y = [J_a_111 * [-uh.dz, uh.dry, uh.drx]'];
d.y = [J_a_111 * [-d.dz, d.dry, d.drx]'];
```

```
% Sampling Time and Frequency
Ts = 1e-4; % [s]
Fs = 1/Ts; % [Hz]
% Hannning Windows
win = hanning(ceil(0.5*Fs));
```

```
Matlab
%% And we get the frequency vector
[G_ur, f] = tfestimate(ur.fjpur, ur.y, win, [], [], 1/Ts);
[G_uh, ~] = tfestimate(uh.fjpuh, uh.y, win, [], [], 1/Ts);
[G_d, ~] = tfestimate(d.fjpd, d.y, win, [], [], 1/Ts);
```

```
Matlab
[coh_ur, ~] = mscohere(ur.fjpur, ur.y, win, [], [], 1/Ts);
[coh_uh, ~] = mscohere(uh.fjpuh, uh.y, win, [], [], 1/Ts);
[coh_d, ~] = mscohere(d.fjpd, d.y, win, [], [], 1/Ts);
```




Figure 2.9: description

```
Matlab
%% Previously used controller
load('X_tal_cage_PID.mat', 'K');
```

```
Matlab
%% Controller design
s = tf('s');

% Lead
a = 8; % Amount of phase lead / width of the phase lead / high frequency gain
wc = 2*pi*20; % Frequency with the maximum phase lead [rad/s]

% Low Pass Filter
w0 = 2*pi*80; % Cut-off frequency [rad/s]
xi = 0.4; % Damping Ratio

Kb = eye(3)*(2*pi*20)^2/(s^2) *1/(sqrt(a))* (1 + s/(wc*sqrt(a)))/(1 + s/(wc*sqrt(a))) * 1/(1 + 2*xi/w0*s + s^2/w0^2);
```

Compare Sensitivity functions

```
Matlab
L = zeros(3, 3, length(f));
Lb = zeros(3, 3, length(f));

for i_f = 1:length(f)
    L(:,:,i_f) = [G_ur(i_f,:); G_uh(i_f,:); G_d(i_f,:)]*freqresp(K, f(i_f), 'Hz');
    Lb(:,:,i_f) = [G_ur(i_f,:); G_uh(i_f,:); G_d(i_f,:)]*freqresp(Kb, f(i_f), 'Hz');
end
```




Figure 2.10: Bode Plot of the DCM dynamics in the frame of the fast jack.




Figure 2.11: Loop gain




Figure 2.12: Loop gain




Figure 2.13: Comparison of sensitivity functions

2.5 Test

```
Matlab
%% Notch
gm = 0.015;
xi = 0.1;
wn = 2*pi*208;
K_notch = (s^2 + 2*gm*xi*wn*s + wn^2)/(s^2 + 2*xi*wn*s + wn^2);
```

```
Matlab
%% Double integrator
w0 = 2*pi*40;
K_int = (w0^2)/(s^2);
```

```
Matlab
%% Lead
a = 3; % Amount of phase lead / width of the phase lead / high frequency gain
K_lead = 1/(sqrt(a))*(1 + s/(w0/sqrt(a)))/(1 + s/(w0*sqrt(a)));
K_lead = K_lead*K_lead;
```

```
Matlab
%% Low Pass Filter
w0 = 2*pi*120; % Cut-off frequency [rad/s]
xi = 0.3; % Damping Ratio
K_lpf = 1/(1 + 2*xi/w0*s + s^2/w0^2);
```




Figure 2.14: Root Locus

```
Matlab
%% Diagonal controller
Kb = 0.8*eye(3)*K_notch*K_int*K_lead*K_lpf;
```

2.6 New controller - Higher bandwidth

```
Matlab
%% Previously used controller
load('X_tal_cage_PID.mat', 'K');
```

```
Matlab
%% Current Controller design
% Lead
a = 8; % Amount of phase lead / width of the phase lead / high frequency gain
wc = 2*pi*20; % Frequency with the maximum phase lead [rad/s]

% Low Pass Filter
w0 = 2*pi*80; % Cut-off frequency [rad/s]
xi = 0.4; % Damping Ratio

Kb_old = eye(3)*(2*pi*20)^2/(s^2) *1/(sqrt(a))* (1 + s/(wc/sqrt(a)))/(1 + s/(wc*sqrt(a))) * 1/(1 + 2*xi/w0*s + s^2/w0^2);;
```

```
Matlab
%% Notch
gm = 0.015;
xi = 0.2;
wn = 2*pi*208;

K_notch = (s^2 + 2*gm*xi*wn*s + wn^2)/(s^2 + 2*xi*wn*s + wn^2);
```

```
Matlab
%% Double integrator
w0 = 2*pi*40;
K_int = (w0^2)/(s^2);
```

```
Matlab
%% Lead
a = 3; % Amount of phase lead / width of the phase lead / high frequency gain
w0 = 2*pi*40;
K_lead = 1/(sqrt(a))*(1 + s/(w0/sqrt(a)))/(1 + s/(w0*sqrt(a)));
K_lead = K_lead*K_lead;
```

```
Matlab
%% Low Pass Filter
w0 = 2*pi*120; % Cut-off frequency [rad/s]
xi = 0.3; % Damping Ratio

K_lpf = 1/(1 + 2*xi/w0*s + s^2/w0^2);
```

```
Matlab
%% Diagonal controller
Kb = 0.9*eye(3)*K_notch*K_int*K_lead*K_lpf;
```

```
Matlab
L = zeros(3, 3, length(f));
Lb = zeros(3, 3, length(f));
Lb_new = zeros(3, 3, length(f));

for i_f = 1:length(f)
    L(:,:,i_f) = [G_ur(i_f,:); G_uh(i_f,:); G_d(i_f,:)]*freqresp(K, f(i_f), 'Hz');
    Lb(:,:,i_f) = [G_ur(i_f,:); G_uh(i_f,:); G_d(i_f,:)]*freqresp(Kb_old, f(i_f), 'Hz');
    Lb_new(:,:,i_f) = [G_ur(i_f,:); G_uh(i_f,:); G_d(i_f,:)]*freqresp(Kb, f(i_f), 'Hz');
end
```

2.7 Added gain

```
Matlab
%% Notch
gm = 0.015;
xi = 0.2;
wn = 2*pi*208;

K_notch = (s^2 + 2*gm*xi*wn*s + wn^2)/(s^2 + 2*xi*wn*s + wn^2);
```




Figure 2.15: description




Figure 2.16: Nyquist Plot




Figure 2.17: description

```
Matlab
%% Double integrator
w0 = 2*pi*40;
K_int = (w0^2)/(s^2);
```

```
Matlab
%% Lead
a = 3; % Amount of phase lead / width of the phase lead / high frequency gain
w0 = 2*pi*40;
K_lead = 1/(sqrt(a))*(1 + s/(w0/sqrt(a)))/(1 + s/(w0*sqrt(a)));
K_lead = K_lead*K_lead;
```

```
Matlab
%% Low Pass Filter
w0 = 2*pi*120; % Cut-off frequency [rad/s]
xi = 0.3; % Damping Ratio
K_lpf = 1/(1 + 2*xi/w0*s + s^2/w0^2);
```

```
Matlab
gm = 10;
xi = 0.02;
wn = 2*pi*15;
H = (s^2 + 2*gm*xi*wn*s + wn^2)/(s^2 + 2*xi*wn*s + wn^2);
```

```
Matlab
%% Diagonal controller
Kb_gain = 0.9*eye(3)*H*K_notch*K_int*K_lead*K_lpf;
```

```
Matlab
Lb_gain = zeros(3, 3, length(f));
for i_f = 1:length(f)
    Lb_gain(:,:,i_f) = [G_ur(i_f,:); G_uh(i_f,:); G_d(i_f,:)]*freqresp(Kb_gain, f(i_f), 'Hz');
end
```




Figure 2.18: description




Figure 2.19: description




Figure 2.20: nyquist plot

3 Noise Budgeting

3.1 No Displacement

```
1  dz311
2  dry311
3  drx311
4  dz111
5  dry111
6  drx111
7  fjpur
8  fpuh
9  fpd
10 bragg
```

```
Matlab _____
data_10_deg = load('no_mov_10.mat');
data_70_deg = load('no_mov_70.mat');
```

```
Matlab _____
data_10_deg = extractDatData('no_mov_10.mat', ...
    {"dz311", "dry311", "drx311", "dz", "dry", "drx", "fjpur", "fpuh", "fpd", "bragg"}, ...
    [1e-9, 1e-9, 1e-9, 1e-9, 1e-9, 1e-9, 1e-8, 1e-8, 1e-8, pi/180]);
data_10_deg = processMeasData(data_10_deg);
```

```
Matlab _____
Ts = 1e-4;
t = Ts*[1:length(data_10_deg.brapp)];
```

```
Matlab _____
data_10_deg.dz = data_10_deg.allValues(:,4) - mean(data_10_deg.allValues(:,4));
data_10_deg.dry = data_10_deg.allValues(:,5) - mean(data_10_deg.allValues(:,5));
data_10_deg.drx = data_10_deg.allValues(:,6) - mean(data_10_deg.allValues(:,6));
```

```
Matlab _____
%% Compute motion error in the frame of the fast jack
J_a_111 = [1, 0.14, -0.1525
            1, 0.14, 0.0675
            1, -0.14, 0.0425];

de_111 = [data_10_deg.dz'; data_10_deg.dry'; data_10_deg.drx'];
de_fj = J_a_111*de_111;
data_10_deg.fj_ur = de_fj(1,:);
data_10_deg.fj_uh = de_fj(2,:);
data_10_deg.fj_d = de_fj(3,:);
```

```

de_111 = [data_70_deg.dz'; data_70_deg.dry'; data_70_deg.drx'];
de_fj = J_a_111*de_111;
data_70_deg.fj_ur = de_fj(1,:);
data_70_deg.fj_uh = de_fj(2,:);
data_70_deg.fj_d = de_fj(3,:);

```

```

Matlab
win = hanning(ceil(1/Ts));

[pxx_10_ur, f] = pwelch(data_10_deg.fj_ur, win, [], [], 1/Ts);
[pxx_70_ur, ~] = pwelch(data_70_deg.fj_ur, win, [], [], 1/Ts);

[pxx_10_uh, ~] = pwelch(data_10_deg.fj_uh, win, [], [], 1/Ts);
[pxx_70_uh, ~] = pwelch(data_70_deg.fj_uh, win, [], [], 1/Ts);

[pxx_10_d, ~] = pwelch(data_10_deg.fj_d, win, [], [], 1/Ts);
[pxx_70_d, ~] = pwelch(data_70_deg.fj_d, win, [], [], 1/Ts);

```

```

Matlab
CPS_10_ur = flip(-cumtrapz(flip(f), flip(pxx_10_ur)));
CPS_10_uh = flip(-cumtrapz(flip(f), flip(pxx_10_uh)));
CPS_10_d = flip(-cumtrapz(flip(f), flip(pxx_10_d)));

CPS_70_ur = flip(-cumtrapz(flip(f), flip(pxx_70_ur)));
CPS_70_uh = flip(-cumtrapz(flip(f), flip(pxx_70_uh)));
CPS_70_d = flip(-cumtrapz(flip(f), flip(pxx_70_d)));

```

```

Matlab
figure;
hold on;
plot(f, sqrt(CPS_10_ur), '--', 'color', colors(1, :), 'DisplayName', '10 deg - $u_r$')
plot(f, sqrt(CPS_70_ur), '--', 'color', colors(1, :), 'DisplayName', '70 deg - $u_r$')
plot(f, sqrt(CPS_10_uh), '--', 'color', colors(2, :), 'DisplayName', '10 deg - $u_h$')
plot(f, sqrt(CPS_70_uh), '--', 'color', colors(2, :), 'DisplayName', '70 deg - $u_h$')
plot(f, sqrt(CPS_10_d), '--', 'color', colors(3, :), 'DisplayName', '10 deg - $d$')
plot(f, sqrt(CPS_70_d), '--', 'color', colors(3, :), 'DisplayName', '70 deg - $d$')
hold off;
set(gca, 'XScale', 'log'); set(gca, 'YScale', 'log');
xlabel('Frequency [Hz]'); ylabel('ASD [$\frac{rad}{\sqrt{Hz}}$]');
legend('location', 'northwest');
xlim([1, 1e3]);

```

```

Matlab
figure;
hold on;
plot(f, sqrt(pxx_10_ur))
plot(f, sqrt(pxx_70_ur))
hold off;
set(gca, 'XScale', 'log'); set(gca, 'YScale', 'log');
xlabel('Frequency [Hz]'); ylabel('ASD [$\frac{rad}{\sqrt{Hz}}$]');
legend('location', 'northwest');
xlim([1, 1e3]);

```

```

Matlab
data_70_deg.dz = data_70_deg.allValues(:,4) - mean(data_70_deg.allValues(:,4));
data_70_deg.dry = data_70_deg.allValues(:,5) - mean(data_70_deg.allValues(:,5));
data_70_deg.drx = data_70_deg.allValues(:,6) - mean(data_70_deg.allValues(:,6));

```

```
Matlab
win = hanning(ceil(1/Ts));

[pxx_10_drx, f] = pwelch(data_10_deg.drx, win, [], [], 1/Ts);
[pxx_70_drx, ~] = pwelch(data_70_deg.drx, win, [], [], 1/Ts);

[pxx_10_dry, ~] = pwelch(data_10_deg.dry, win, [], [], 1/Ts);
[pxx_70_dry, ~] = pwelch(data_70_deg.dry, win, [], [], 1/Ts);

[pxx_10_dz, ~] = pwelch(data_10_deg.dz, win, [], [], 1/Ts);
[pxx_70_dz, ~] = pwelch(data_70_deg.dz, win, [], [], 1/Ts);
```

```
Matlab
figure;
hold on;
plot(f, sqrt(pxx_10_drx))
plot(f, sqrt(pxx_70_drx))
hold off;
set(gca, 'XScale', 'log'); set(gca, 'YScale', 'log');
xlabel('Frequency [Hz]'); ylabel('ASD [$\frac{nrad}{\sqrt{Hz}}$]');
legend('location', 'northwest');
xlim([1, 1e3]);
```

```
Matlab
figure;
hold on;
plot(f, sqrt(pxx_10_dry))
plot(f, sqrt(pxx_70_dry))
hold off;
set(gca, 'XScale', 'log'); set(gca, 'YScale', 'log');
xlabel('Frequency [Hz]'); ylabel('ASD [$\frac{nrad}{\sqrt{Hz}}$]');
legend('location', 'northwest');
xlim([1, 1e3]);
```

```
Matlab
figure;
hold on;
plot(f, sqrt(pxx_10_dz))
plot(f, sqrt(pxx_70_dz))
hold off;
set(gca, 'XScale', 'log'); set(gca, 'YScale', 'log');
xlabel('Frequency [Hz]'); ylabel('ASD [$\frac{nm}{\sqrt{Hz}}$]');
legend('location', 'northwest');
xlim([1, 1e3]);
```

3.2 Scans

- | | |
|----|--------|
| 1 | dz311 |
| 2 | dry311 |
| 3 | drx311 |
| 4 | dz111 |
| 5 | dry111 |
| 6 | drx111 |
| 7 | fjpur |
| 8 | fjpuh |
| 9 | fjpd |
| 10 | bragg |

```

----- Matlab -----
%% Load Data
data_10_70_deg = extractDatData('thtraj_10_70.mat', ...
    {"dz311", "dry311", "drx311", "dz", "dry", "drx", "fjur", "fjuh", "fjd", "bragg"}, ...
    [1e-9, 1e-9, 1e-9, 1e-9, 1e-9, 1e-8, 1e-8, 1e-8, pi/180]);

Ts = 1e-4;
t = Ts*[1:length(data_10_70_deg.bragg)];

%% Actuator Jacobian
J_a_111 = [1, 0.14, -0.0675
            1, 0.14, 0.1525
            1, -0.14, 0.0425];

data_10_70_deg.ddz = 10.5e-3./(2*cos(data_10_70_deg.bragg)) - data_10_70_deg.dz;

%% Computation of the position of the FJ as measured by the interferometers
error = J_a_111 * [data_10_70_deg.ddz, data_10_70_deg.dry, data_10_70_deg.drx]';

data_10_70_deg.fjur_e = error(1,:); % [m]
data_10_70_deg.fjuh_e = error(2,:); % [m]
data_10_70_deg.fjd_e = error(3,:); % [m]

```

```

----- Matlab -----
%% Load Data
data_70_10_deg = extractDatData('thtraj_70_10.mat', ...
    {"dz311", "dry311", "drx311", "dz", "dry", "drx", "fjur", "fjuh", "fjd", "bragg"}, ...
    [1e-9, 1e-9, 1e-9, 1e-9, 1e-9, 1e-8, 1e-8, 1e-8, pi/180]);

%% Actuator Jacobian
J_a_111 = [1, 0.14, -0.0675
            1, 0.14, 0.1525
            1, -0.14, 0.0425];

data_70_10_deg.ddz = 10.5e-3./(2*cos(data_70_10_deg.bragg)) - data_70_10_deg.dz;

%% Computation of the position of the FJ as measured by the interferometers
error = J_a_111 * [data_70_10_deg.ddz, data_70_10_deg.dry, data_70_10_deg.drx]';

data_70_10_deg.fjur_e = error(1,:); % [m]
data_70_10_deg.fjuh_e = error(2,:); % [m]
data_70_10_deg.fjd_e = error(3,:); % [m]

```

```

----- Matlab -----
win = hanning(ceil(1/Ts));

[pxx_10_70_ur, f] = pwelch(data_10_70_deg.fjur_e(t<100), win, [], [], 1/Ts);
[pxx_70_10_ur, ~] = pwelch(data_70_10_deg.fjur_e(t<100), win, [], [], 1/Ts);

[pxx_10_70_uh, ~] = pwelch(data_10_70_deg.fjuh_e(t<100), win, [], [], 1/Ts);
[pxx_70_10_uh, ~] = pwelch(data_70_10_deg.fjuh_e(t<100), win, [], [], 1/Ts);

[pxx_10_70_d, ~] = pwelch(data_10_70_deg.fjd_e(t<100), win, [], [], 1/Ts);
[pxx_70_10_d, ~] = pwelch(data_70_10_deg.fjd_e(t<100), win, [], [], 1/Ts);

```

```

----- Matlab -----
CPS_10_70_ur = flip(-cumtrapz(flip(f), flip(pxx_10_70_ur)));
CPS_10_70_uh = flip(-cumtrapz(flip(f), flip(pxx_10_70_uh)));
CPS_10_70_d = flip(-cumtrapz(flip(f), flip(pxx_10_70_d)));

CPS_70_10_ur = flip(-cumtrapz(flip(f), flip(pxx_70_10_ur)));
CPS_70_10_uh = flip(-cumtrapz(flip(f), flip(pxx_70_10_uh)));
CPS_70_10_d = flip(-cumtrapz(flip(f), flip(pxx_70_10_d)));

```

```

----- Matlab -----
figure;
hold on;

```

```

plot(f, 1e9*sqrt(CPS_10_70_ur))
hold off;
set(gca, 'XScale', 'log'); set(gca, 'YScale', 'log');
xlabel('Frequency [Hz]'); ylabel('ASD [$\frac{m}{rad}\{\sqrt{Hz}\}$]');
legend('location', 'northwest');
xlim([1, 1e3]);

```

Matlab

```

figure;
hold on;
plot(f, sqrt(pxx_10_70_ur))
plot(f, sqrt(pxx_70_10_ur))
hold off;
set(gca, 'XScale', 'log'); set(gca, 'YScale', 'log');
xlabel('Frequency [Hz]'); ylabel('ASD [$\frac{m}{rad}\{\sqrt{Hz}\}$]');
legend('location', 'northwest');
xlim([1, 1e3]);

```

3.3 Noise budgeting - No rotation

First, we look at the position errors when the bragg axis is not moving

```

%% Load Measurement Data
ol_data = load('FJPUR_step.mat');

```

Matlab

```

%% Pre-processing
ol_time = ol_data.time - ol_data.time(1);

ol_drx = ol_data.allValues(ol_time < 45, 6);
ol_dry = ol_data.allValues(ol_time < 45, 5);
ol_dz = ol_data.allValues(ol_time < 45, 4);

ol_drx = ol_drx - mean(ol_drx);
ol_dry = ol_dry - mean(ol_dry);
ol_dz = ol_dz - mean(ol_dz);

ol_time = ol_time(ol_time < 45);

```

Matlab

```

figure;
plot(ol_time, ol_drx)

```

Matlab

```

%% Parameters for Spectral Analysis
Ts = 1e-4;
win = hanning(ceil(1/Ts));

```

Matlab

```

%% Computation of the PSD
[pxx_ol_drx, f] = pwelch(ol_drx, win, [], [], 1/Ts);
[pxx_ol_dry, ~] = pwelch(ol_dry, win, [], [], 1/Ts);
[pxx_ol_dz, ~] = pwelch(ol_dz, win, [], [], 1/Ts);

```




Figure 3.1: Amplitude Spectral Density

```
Matlab
%% Cumulative Spectral Density
CPS_drx = flip(-cumtrapz(flip(f), flip(pxx_ol_drx)));
CPS_dry = flip(-cumtrapz(flip(f), flip(pxx_ol_dry)));
CPS_dz = flip(-cumtrapz(flip(f), flip(pxx_ol_dz)));
```

```
Matlab
%% Cumulative Spectral Density
CPS_drx = cumtrapz(f, pxx_ol_drx);
CPS_dry = cumtrapz(f, pxx_ol_dry);
CPS_dz = cumtrapz(f, pxx_ol_dz);
```




Figure 3.2: Cumulative Amplitude Spectrum

3.4 Noise budgeting - Bragg rotation

4 Test Mode C

4.1 Mode B and Mode C

```
Matlab
data_B =
→ extractDatData(sprintf("/home/thomas/mnt/data_id21/22Jan/blc13491/id21/test_regul_220119/%s","lut_const_fj_vel_19012022_1450.dat"),
→ ...
   {"bragg", "dz", "dry", "drx", "fjur", "fjuh", "fjd"}, ...
   [pi/180, 1e-9, 1e-9, 1e-9, 1e-8, 1e-8, 1e-8]);
data_B = processMeasData(data_B);
```

```
Matlab
data_C =
→ extractDatData(sprintf("/home/thomas/mnt/data_id21/22Jan/blc13491/id21/test_regul_220119/%s","lut_const_fj_vel_19012022_1454.dat"),
→ ...
   {"bragg", "dz", "dry", "drx", "fjur", "fjuh", "fjd"}, ...
   [pi/180, 1e-9, 1e-9, 1e-9, 1e-8, 1e-8, 1e-8]);
data_C = processMeasData(data_C);
```

```
Matlab
figure;
hold on;
plot(180/pi*data_B.bragg, 1e9*data_B.drx)
hold off;
xlabel('Bragg Angle [deg]'); ylabel('DRX [nrad]');
```

```
Matlab
figure;
hold on;
plot(180/pi*data_B.bragg, 1e9*data_B.fjur_e_filt)
plot(180/pi*data_C.bragg, 1e9*data_C.fjur_e_filt)
hold off;
xlabel('Bragg Angle [deg]'); ylabel('FJUR Error [nm]');
```

```
Matlab
figure;
hold on;
plot(180/pi*data_B.bragg, 1e9*data_B.fjur_e)
plot(180/pi*data_C.bragg, 1e9*data_C.fjur_e)
hold off;
xlabel('Bragg Angle [deg]'); ylabel('FJUR Error [nm]');
```

```
Matlab
%% FIR Filter
Fs = 1e4; % Sampling Frequency [Hz]
fir_order = 5000; % Filter's order
delay = fir_order/2; % Delay induced by the filter
```

```
B_fir = firls(5000, ... % Filter's order  
[0 5/(Fs/2) 10/(Fs/2) 1], ... % Frequencies [Hz]  
[1 1 0 0]); % Wanted Magnitudes
```

```
Matlab _____  
%% Filtering all measured Fast Jack Position using the FIR filter  
data_B.drx_filter = filter(B_fir, 1, data_B.drx);  
data_B.drx_filter(1:end-delay) = data_B.drx_filter(delay+1:end);  
  
data_C.drx_filter = filter(B_fir, 1, data_C.drx);  
data_C.drx_filter(1:end-delay) = data_C.drx_filter(delay+1:end);
```

```
Matlab _____  
figure;  
hold on;  
plot(180/pi*data_B.bragg, 1e9*data_B.drx_filter)  
plot(180/pi*data_C.bragg, 1e9*data_C.drx_filter)  
hold off;  
xlabel('Bragg Angle [deg]'); ylabel('DRX [nrad]');
```

```
Matlab _____  
Ts = 1e-4;  
win = hanning(ceil(1/Ts));  
  
[pxx_B_drx, f] = pwelch(data_B.drx, win, [], [], 1/Ts);  
[pxx_C_drx, ~] = pwelch(data_C.drx, win, [], [], 1/Ts);
```

5 Export numerator and denominator

5.1 Export

```
K_order = 10;
```

```
load('X_tal_cage_PID.mat', 'K');
K_order = order(K(1,1));
Kz = c2d(K(1,1)*(1 + s/2/pi/2e3)^(9-K_order)/(1 + s/2/pi/2e3)^(9-K_order), 1e-4);
[num, den] = tfdata(Kz, 'v');

formatSpec = '%.18e %.18e %.18e %.18e %.18e %.18e %.18e %.18e %.18e %.18e\n';
fileID = fopen('X_tal_cage_PID.dat', 'w');
fprintf(fileID, formatSpec, [num; den]);
fclose(fileID);
```

```
load('X_tal_cage_PID_20Hz.mat', 'K');
K_order = order(K(1,1));
Kz = c2d(K(1,1)*(1 + s/2/pi/2e3)^(9-K_order)/(1 + s/2/pi/2e3)^(9-K_order), 1e-4);
[num, den] = tfdata(Kz, 'v');

formatSpec = '%.18e %.18e %.18e %.18e %.18e %.18e %.18e %.18e %.18e %.18e\n';
fileID = fopen('X_tal_cage_PID_20Hz.dat', 'w');
fprintf(fileID, formatSpec, [num; den]);
fclose(fileID);
```

```
load('X_tal_cage_PID_40Hz.mat', 'K');
K_order = order(K(1,1));
Kz = c2d(K(1,1)*(1 + s/2/pi/2e3)^(9-K_order)/(1 + s/2/pi/2e3)^(9-K_order), 1e-4);
[num, den] = tfdata(Kz, 'v');

formatSpec = '%.18e %.18e %.18e %.18e %.18e %.18e %.18e %.18e %.18e %.18e\n';
fileID = fopen('X_tal_cage_PID_40Hz.dat', 'w');
fprintf(fileID, formatSpec, [num; den]);
fclose(fileID);
```

5.2 Verify

```
K_data = importdata('X_tal_cage_PID_20Hz.dat');
K = tf(K_data(1,:), K_data(2,:), 1e-4)
```