


ID31 microstation – 20th, November 2017

Measurements made in the following conditions:

- The granite is not glued on the floor
- The Y translation is powered and in close loop
- The spindle is not powered



The 4 accelerometers



Excitation along X